

Inspection Photos

API: 017-06636

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 3/26/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



Inspection Photos



Photo 2. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



Inspection Photos



Photo 3. Facing west along the road toward the wellsite. There is an erosion channel coming from the wellsite along the road that will need to be repaired and stabilized.



Inspection Photos



Photo 4. There is stained soils from a leak occurring from the pumpjack engine.



Inspection Photos



Photo 5. View of inside the shed shows oil saturated soils from the leaking engine.



Inspection Photos



Photo 6. Facing toward the wellhead. The well sign is laying on the ground. The barrel is not properly set in the containment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos




Photo 7. Facing toward the electric utility just south of the well. The electric wire is on the surface and not protected which is a safety concern. The electric breaker is disconnected from the electric line.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06636 | Date: 3/26/2024

Inspection Photos



Photo 8. Facing east at the erosion channel occurring along the access road. The red arrow points to a 4.5 ft. shovel for scale.

