

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

02/27/2024

Document Number:

403699543

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 46290 Contact Person: Mani Silva
Company Name: KP KAUFFMAN COMPANY INC Phone: (303) 8254822
Address: 1700 LINCOLN ST STE 4550 Email: regulatory@kpk.com
City: DENVER State: CO Zip: 80203
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 444947 Location Type: Production Facilities
Name: North Quebec TB Number: _____
County: ADAMS
Qtr Qtr: NESE Section: 8 Township: 1S Range: 67W Meridian: 6
Latitude: 39.976330 Longitude: -104.903480

Description of Corrosion Protection

Carbon Steel pipelines are typically covered with a protective external coating, and are subject to rigorous fabrication, inspection, and quality control standards to reduce the occurrence of pipe and coating defects that can lead to external corrosion. While the likelihood of corrosion is minimal due to low operating pressures, KPK regularly inspects and pressure tests all lines to ensure corrosion is not occurring.

Description of Integrity Management Program

Production and upkeep of KPK's assets involves regular hands-on operation by KPK's field crews. These field crews not only maintain safe production, but also conduct routine inspections to confirm proper integrity of the production systems. While pipeline integrity issues are minimal due to pipeline materials and low operating pressure, KPK regularly inspects and pressure tests all lines to ensure pipeline integrity is maintained.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

Construction of pipelines is generally not occurring. When necessary to remedy a pipeline issue, KPK typically assesses all conditions to determine the proper construction method. A combination of boring and open trench are utilized by KPK.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 476097 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 335735 Location Type: Well Site ☐
Name: TALON POINT Number: 15-8
County: ADAMS No Location ID
Qtr Qtr: SWSE Section: 8 Township: 1S Range: 67W Meridian: 6
Latitude: 39.974361 Longitude: -104.908833

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 03/10/2008
Maximum Anticipated Operating Pressure (PSI): Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 05/08/2022

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The developer has requested all underground lines be removed. We will fully remove all flowlines after the wells are P&A'd.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 476098 Flowline Type: Wellhead Line Action Type: Pre-Abandonment Notice

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 320484 Location Type: Well Site ☐
Name: NORTH QUEBEC-61S67W Number: 8NESE
County: ADAMS No Location ID
Qtr Qtr: NESE Section: 8 Township: 1S Range: 67W Meridian: 6
Latitude: 39.977869 Longitude: -104.905642

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Native Materials Date Construction Completed: 10/02/2001
Maximum Anticipated Operating Pressure (PSI): Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Pre-Abandonment Notice

Date: 03/28/2023

Pre-Abandonment 30-day Notice☒ Removed per Rule 1105.d.(2)☐ Abandoned In Place per Rule 1105.d.(2) Exceptions - select all that apply:

- ☐ A. A surface owner agreement executed by a surface owner allows abandonment in place.
- ☐ B. The line is subject to the jurisdiction of the federal government, and the relevant federal agency directs abandonment in place.
- ☐ C. The flowline or crude oil transfer line is co-located with other active pipelines or utilities or is in a recorded right of way.
- ☐ D. Removal of the line would cause significant damage to natural resources, including wildlife resources, topsoil, or vegetation.
- ☐ E. The flowline or crude oil transfer line is in a restricted surface occupancy area or sensitive wildlife habitat.
- ☐ F. The flowline or crude oil transfer line or a segment of the line crosses or is within 30 feet of a public road, railroad, bike path, public right of way, utility corridor, or active utility or pipeline crossing.
- ☐ G. The flowline or crude oil transfer line or a segment of the line crosses or is within 30 feet of or from under a river, stream, lake, pond, reservoir, wetlands, watercourse, waterway, or spring.
- ☐ H. The operator demonstrates and quantifies that the removal of the flowline will cause significant emissions of air pollutants.

☐ Abandoned In Place per Rule 1105.d.(3)**Description of Pre-Abandonment Notice:**

Now that the well has been abandoned we will plan to excavate the flowline in 50 foot increments. The flowline will be cut and pulled through these segments to the surface. Contaminated soil will be contained, disposed of, and replaced. The goal is to leave the area looking as undisturbed as possible.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 476099 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 319670 Location Type: Well Site ☐

Name: N QUEBEC-61S67W Number: 8NWSE

County: ADAMS No Location ID

Qtr Qtr: NWSE Section: 8 Township: 1S Range: 67W Meridian: 6

Latitude: 39.977319 Longitude: -104.910352

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000

Bedding Material: Native Materials Date Construction Completed: 01/21/1976

Maximum Anticipated Operating Pressure (PSI): Testing PSI:

Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

OPERATOR COMMENTS AND SUBMITTAL

Comments

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 02/27/2024 Email: tjkilian@kpk.com

Print Name: TJ Kilian Title: Field Engineer

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  **Director of COGCC** Date: 3/28/2024

Condtions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

403699543	Form44 Submitted
403699558	OFF-LOCATION FLOWLINE GIS KML

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)