

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2024

Submitted Date:

03/21/2024

Document Number:

707901447

**FIELD INSPECTION FORM**Loc ID 336455 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240045	WELL	PR	02/01/2021	OW	123-07833	JAMES A DAMIANA 1	SI

**General Comment:**

Follow up inspection to complaint doc#403678795 and inspection doc# 707901327

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	OTHER			
Comment:		None reporting FIRR		
Corrective Action:		Rule 210		Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				corrective date
Type: Other	#			
Comment:		Equipment does not appear to have changed at time of inspection.		
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**Facility ID: 240045 Type: WELL API Number: 123-07833 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: At time of inspection well head flow line valves appear to be in the closed position. At time of inspection Hoz Sep had no pressure and was not in operation.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 07/06/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<u>This is a follow up inspection per doc#707901327. At time of inspection it appears the only corrective addressed was the fencing issue dealing with compliant doc# 403678795. All previous corrective actions still remain. KPK has failed to submit FIRR as to the date of cattle panels being installed. KPK is being issued additional corrective action for none reporting of FIRR Rule 210 and is out of compliance of all other corrective action in inspection doc#707901327 completion date of 3-7-24. This location compliance issue with be moved for further action NOAV.</u>	silverr	03/21/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403728246	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477551</a>
707901448	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477549">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477549</a>