

# Inspection Photos

Loc: 321574

Operator: MULL DRILLING COMPANY INC

Inspection Date: 3/26/2024

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south toward wellsite location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321574 | Date: 3/26/2024

Inspection Photos



**Photo 2.** Facing toward the wellhead.



## Inspection Photos



**Photo 3.** Facing northwest. There is an open excavation along the pipeline. There is an orange safety fence installed around the excavation.



Inspection Photos



**Photo 4.** Facing toward the equipment at the south side of the location..



## Inspection Photos



**Photo 5.** Facing toward the open top tank where the spill was observed during previous inspection. There is fresh sandy material that was spread over this area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321574 | Date: 3/26/2024

## Inspection Photos



**Photo 6.** There is still oily soils and it appears material was spread over the spill to cover it up.



**Photo 7.** View of oily soils still found by the open top tank.



## Inspection Photos



**Photo 8.** The red arrows point to areas where oily soils have not been cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321574 | Date: 3/26/2024