

Inspection Photos

Loc: 381172

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/26/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 21. Facing northeast along the two track access road. There is an erosion channel along the road closer to the location that needs to be repaired.



Inspection Photos



Photo 2. Facing northeast at the location. This area has not been reclaimed and perennial vegetation has not established. The cut slope can be seen at the red arrow.



Inspection Photos



Photo 3. Facing north along the cut slope which is eroded and has not been regraded back to approximate grade..



Inspection Photos



Photo 4. North side of the location facing southwest. There is some cement block debris and a bare area shown at red arrows.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:381172 | Date: 3/26/2024

Inspection Photos



Photo 5. Northwest side of the location facing southeast. There is an erosion channel along this area and soils are bare of vegetation.



Inspection Photos



Photo 6. Facing east at the location. The location has not been reclaimed and perennial vegetation has not established.



Inspection Photos



Photo 8. Facing east at the location. The location has not been reclaimed and perennial vegetation has not established.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:381172 | Date: 3/26/2024