

Inspection Photos

Loc: 321575

Operator: MULL DRILLING COMPANY INC

Inspection Date: 3/26/2024

County: CHEYENNE



Inspection Photos



Photo 1. Facing west toward wellsite location.



Inspection Photos



Photo 3. The secondary containment has been cleaned out and weeds removed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321575 | Date: 3/26/2024

Inspection Photos



Photo 4. The secondary containment has been cleaned out..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321575 | Date: 3/26/2024

Inspection Photos



Photo 4. There is an area of disturbance along the flowline that will need to be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321575 | Date: 3/26/2024