

# Inspection Photos

API: 017-06652

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 3/26/2024

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south at the beginning of the access road. The cattleguard will need to be removed and fence installed back to original position. The road needs to be reclaimed.





## Inspection Photos



**Photo 2.** Facing south along the access road. The two track access road remains and will need to be decompacted. Consider decompacted only to two track portion to save vegetated areas.





## Inspection Photos



**Photo 3.** Facing west along the access road. This portion of the road has revegetated.





## Inspection Photos



**Photo 4.** Facing north at the location. The cut slope has not been recontoured back to the original terrain contours.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 5.** Facing west at center of the location. This area does not have sufficient vegetation establishment and needs to be reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 6.** Facing east at center of the location. This area does not have sufficient vegetation establishment and needs to be reclaimed.





## Inspection Photos



**Photo 7.** Facing southeast at the top of the cut slope. There is a berm along the top which needs to be recontoured along the cut slope.





## Inspection Photos



**Photo 8.** Facing south at the top of the cut slope. There is a berm along the top of the which needs to be recontoured along the cut slope.





## Inspection Photos



**Photo 9.** Facing north toward the surrounding undisturbed reference area.

