

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location ID: 335390

Date: 3/26/2024



Location Entrance – Photo #00112



Wellheads – Photo #00113

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location ID: 335390

Date: 3/26/2024



Separators – Photo #00116



Tank Battery – Photo #00115

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location ID: 335390

Date: 3/26/2024



Lack of Stabilization/Degradation – Photo #00114



Lack of Stabilization/Degradation – Photo #00117

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SWNE

Location ID: 335390

Date: 3/26/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00118