

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/28/2024

Submitted Date:

03/29/2024

Document Number:

693806980

FIELD INSPECTION FORMLoc ID 314673 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10779

Name of Operator: SCOUT ENERGY MANAGEMENT LLC

Address: 13800 MONTFORT DRIVE SUITE 100

City: DALLAS State: TX Zip: 75240

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Johnson, Mike	972-674-8679	Mike.Johnson@scoutep.com	Regional Manager
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229233	WELL	IJ	08/12/2022	ERIW	103-06324	MCLAUGHLIN, A C 43	AC

General Comment:

Routine UIC inspection.

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign at WAG skid		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-675-3700		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 1		corrective date
Comment:	WAG skid		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 229233

Type: WELL

API Number: 103-06324

Status: IJ

Insp. Status: AC

Underground Injection Control

UIC Violation:

Maximum Injection Pressure:

UIC Routine

Inj./Tube:

Pressure or inches of Hg 1422

Previous Test Pressure

MPP

(e.g. 30 psig or -30" Hg)

Inj Zone: WEBR

TC:

Pressure or inches of Hg 0

Previous Test Pressure

Last MIT: 09/20/2023

Brhd:

Pressure or inches of Hg 0

Previous Test Pressure

AnnMTReq:

Comment:

Routine UIC inspection. Active injection at time of inspection.

Corrective Action:

Date:

Method of Injection: PUMP FEED

Test Type:

Tbg psi:

Csg psi:

BH psi:

Insp. Status:

Comment:

Corrective Action:

Date:

Date Run: 3/29/2024 Doc [#693806980]

Page 4 of 5

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693806981	Inspection photos 3/28/2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487435