

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/28/2024

Submitted Date:

03/29/2024

Document Number:

693806985

**FIELD INSPECTION FORM**

Loc ID 314261 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10779  
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC  
 Address: 13800 MONTFORT DRIVE SUITE 100  
 City: DALLAS State: TX Zip: 75240

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita	970-640-3572	anita.sanford@scoutep.com	Regulatory Specialist
Labowskie, Steve		steve.labowskie@state.co.us	
Taylor, Chad	(720) 788-6197	chad.taylor@state.co.us	Underground Injection Lead
Johnson, Mike	972-674-8679	Mike.Johnson@scoutep.com	Regional Manager
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228137	WELL	IJ	10/18/2021	ERIW	103-01055	MCLAUGHLIN, A C 22	AC

**General Comment:**

Routine UIC inspection.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action			Date:
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	WAG skid		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:	Date:
--------------------	-------

--

**Inspected Facilities**

Facility ID: 228137 Type: WELL API Number: 103-01055 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube:	Pressure or inches of Hg <u>1535</u>	Previous Test Pressure _____	MPP _____
	(e.g. 30 psig or -30" Hg)		Inj Zone: <u>WEBR</u>
TC:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	Last MIT: <u>09/30/2021</u>
Brhd:	Pressure or inches of Hg <u>0</u>	Previous Test Pressure _____	AnnMTReq: _____

Comment: Routine UIC inspection. Active injection at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693806986	Inspection photos 3/28/2024	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487437">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6487437</a>