

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 3/26/2024



Location Entrance – Photo #00144



Wellheads – Photo #00145

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 3/26/2024



Separators – Photo #00149



Tank Battery – Photo #00147

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 3/26/2024



**Hog Panel Debris – Photo #00146**



**Open-Ended Line in Tank Battery – Photo #00153**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 3/26/2024



**Insufficient Erosion Control/Degradation – Photo #00150**



**Insufficient Erosion Control/Degradation – Photo #00151**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 3/26/2024



**Insufficient Erosion Control on Lease Road Cut Slopes –  
Photo #00155**



**Soil Stockpiled on Lease Road – Photo #00156**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Puckett/GM 333-31

Location ID: 416998

Date: 3/26/2024



Mar 26, 2024 at 13:17:52

**Soil Stockpiled on Lease Road – Photo #00157**