

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2024

Submitted Date:

03/29/2024

Document Number:

693701146**FIELD INSPECTION FORM**Loc ID 416234 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Peterson, Dan		danpeterson@chevron.com	
, Environmental		rbuef27@chevron.com	
, Inspections		rbucogccinspectionreports@c hevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416259	WELL	SI	09/01/2017	OW	123-31318	Shable USX AB 11-12P	EI

General Comment:

Inspected Facilities									
Facility ID:	416259	Type:	WELL	API Number:	123-31318	Status:	SI	Insp. Status:	EI

--

Environmental

Spill/Remediation:

Comment:

ECMC Environmental Inspection Remediation Project 30814 for well plugging, cut & cap and Rule 911 assessment. Well site is backfilled.

Operator reported a historical release associated with the well flowline on 1/19/2024 via email and Initial Form 19 Document #403660755. The Form 19 indicated a Release at the flowline point at the well site, and within the flowline corridor but was unclear whether Supplemental Form 19 was meant to encompass both release points. ECMC returned Form 19 Document #403660755 to Draft status on 1/23/2024 for clarifications regarding exact spill location(s). Form 19 Document #403660755 has not been resubmitted.

ECMC received a Supplemental Form 27 Document #403660157 on 1/19/2024 that appeared intended to address the Spill at the flowline. ECMC returned Form 27 Document #403660157 to draft status on 1/23/2024. Operator resubmitted Form 27 on 1/26/2024, and ECMC approved the Form 27 on 3/29/2024. This Form 27 does not include well assessment results. Form 6 Document # 403621899 indicated well was cut and capped 11/9/2023.

Corrective Action:

Operator shall submit well assessment data within 30 days (April 28, 2024) on a Supplemental Form 27.

Resubmit the Initial Form 19 addressing the requested corrections for the flowline release. This release remains undocumented by the Form 19 (immediate).

Date:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
693701147	ShableUSXAB11-12P_wellsite_3-22-2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488802
693701148	ShableUSXAB11-12P_flowlinesite_3-22-2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488803

Date Run: 4/1/2024 Doc [#693701146]

Page 3 of 3