

Inspected Facilities

Facility ID: 417949 Type: WELL API Number: 123-31799 Status: SI Insp. Status: EI

Environmental

Spill/Remediation:

Comment: ECMC Environmental Inspection Remediation Project 30810 for well plugging, cut & cap and Rule 911 assessment. Well site is backfilled.

Operator reported a historical release associated with the well flowline on 1/19/2024 via email and Initial Form 19 Document #403660384. The Form 19 latitude/longitude indicated a Release at the flowline point at the well site, but included data indicated a release within the flowline corridor and was unclear which Release Form 19 was meant to document. ECMC returned Form 19 Document #403660384 to Draft status on 1/23/2024 for clarifications regarding exact spill location(s). Form 19 Document #403660384 has not been resubmitted.

ECMC received a Supplemental Form 27 Document #403660099 on 1/19/2024 that appeared intended to address the Spill at the flowline. ECMC returned Form 27 Document #403660099 to draft status on 1/23/2024. Operator resubmitted Form 27 on 1/26/2024, and ECMC approved the Form 27 on 3/29/2024 approving consolidation of flowline release point onto Remediation Project 30814.

This Form 27 does not include well assessment results. Form 6 Document # 403621199 indicated well was cut and capped 11/9/2023.

Corrective Action: Operator shall submit well assessment data within 30 days (April 28, 2024) on a Supplemental Form 27.

Resubmit the Initial Form 19 addressing the requested corrections for the flowline release if applicable, or submit FIRR documenting Form 19 would be duplicative of Form 29 Document #403660755, if appropriate. This release potentially remains undocumented by the Form 19.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ **Wildlife Protection Devices (fired vessels):** _____