

Inspected Facilities

Facility ID: 297683 Type: WELL API Number: 123-28034 Status: TA Insp. Status: EI

Facility ID: 485371 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [ECMC Environmental Inspection Remediation Project 30764 for well plugging, cut & cap and Rule 911 assessment. Historical release was reported 10/20/2023. Well site is backfilled. ECMC received a Supplemental Form 27 11/17/2023/approved on 1/17/2024 with a proposal for further site assessment. ECMC expects a Supplemental Form 27 4/16/2024, 90 days after the last Supplemental Form 27 was approved.](#)

[ECMC notes flowline was abandoned prior to January 15, 2024 according to Initial Form 27 Document #403465222.](#)

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693701139	Shable14-13wellsite3-22-2024(2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488797
693701140	Shable14-13wellsite3-22-2024(1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488798