

Final Reclamation Inspection

March 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326198

Inspection Document #: 714000619

La Plata County, CO

Township: SESE 36 33N 11W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Eldridge 36-02 1
Location ID: 326198



Photo 1. Overview of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Eldridge 36-02 1
Location ID: 326198



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the northern interim reclamation area facing east.
Vegetation comprised of crested wheatgrass, indian rice grass, rabbit brush
and sage brush.

API #: 067-07631

Inspection Photos
Location Name: Eldridge 36-02 1
Location ID: 326198

3/28/24
+37.057142,-107.987899
225° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Waste/debris corrective action identified in the previous inspection doc #693903403 has been addressed/resolved.

API #: 067-07631

Inspection Photos
Location Name: Eldridge 36-02 1
Location ID: 326198



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Rill erosion observed forming along the fence line of the produced water tank.

API #: 067-07631

Inspection Photos
Location Name: Eldridge 36-02 1
Location ID: 326198



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Plastic and foam waste/debris observed along the sound wall.

API #: 067-07631

Inspection Photos
Location Name: Eldridge 36-02 1
Location ID: 326198



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area comprised of rabbitbrush, sage brush, crested wheatgrass and indian ricegrass.

API #: 067-07631