

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2024

Submitted Date:

04/01/2024

Document Number:

698601793

**FIELD INSPECTION FORM**

Loc ID 311034 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298183	WELL	PR	05/13/2011	GW	125-11427	BROWN 13-02 1N47W	PR

**General Comment:**

Routine inspection.

<b>Location</b>			
<b>Lease Road:</b>			
	Type	Access	
	comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.	
	Corrective Action:		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type	WELLHEAD	
	Comment:	Well sign located at wellhead.	
	Corrective Action:		Date:
	Type	OTHER	
	Comment:	Well sign posted at remote gas meter run.	
	Corrective Action:		Date:
<b>Emergency Contact Number:</b>			
	Comment:	Emergency contact information posted on both the Well location and Meter Run signs.	
	Corrective Action:		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
	Comment:		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type	WELLHEAD	
	Comment:	Stock panel fencing around surface equipment at well location.	
	Corrective Action:		Date:
<b>Equipment:</b>			
Type: Ancillary equipment # 1			corrective date
	Comment:	Wellhead. Rods and tubing in the wellbore. Tubing valve not connected. Casing valve open.	
	Corrective Action:		Date:
Type: Dehydrator # 1			
	Comment:	Dehydrator on gas meter run inlet.	
	Corrective Action:		Date:
Type: Gas Meter Run # 1			
	Comment:	Remote Gas Meter Run located on CR 35 and CR M. Gas Meter Run. Chart in Meter Box dated 3-1-24. Meter Calibration/Test Log dated 12-5-23. Well Inlet Valve open. Gas Outlet Valve open.	
	Corrective Action:		Date:
Type: Pump Jack # 1			

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Pump Jack Power and Control Panel.		
Corrective Action:			Date:
Type: Vertical Separator	# 0		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric Motor.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Shared Remote Gas Meter Shed.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Pump Jack welded steel pipe base.		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Riser with valve and plug at wellhead.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 298183 Type: WELL API Number: 125-11427 Status: PR Insp. Status: PR

**Producing Well**

Comment: Rods and tubing in wellbore. Tubing valve not connected. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.

Electronic Well File reflects last Production/Status reported 1/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601865	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490047">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490047</a>