

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2024

Submitted Date:

04/01/2024

Document Number:

713300773

FIELD INSPECTION FORM

Loc ID 318401 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Silver, Randy	720-827-6688	randy.silver@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241231	WELL	PR	09/01/2023	OW	123-09019	UPRR 43 PAN AM I 8	PR

General Comment:

[Follow up inspection, 698705907](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	
Type	OTHER		
Comment:	electric/automation disconnects		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date	corrective date
Pump Jack	# 1				
		Comment:			
		Corrective Action:		Date:	
Bradenhead	# 1				
		Comment: piped to surface			
		Corrective Action:		Date:	
Prime Mover	# 1				
		Comment: electric motor			
		Corrective Action:		Date:	
Ancillary equipment	# 3				
		Comment: automation/electric panels			
		Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241231 Type: WELL API Number: 123-09019 Status: PR Insp. Status: PR

Producing Well

Comment: PR Valves appeared to be open at time of inspection
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/23/2023 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: submit report
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p><u>ECMC Inspection Report Summary</u> Inspector Michael Kester, conducted on-site Follow up inspection as per Doc 698705907, corrective actions appeared to have been addressed. Location: UPRR 43 PanAm I 8 Operator: KPK API#: 123-09019 County: Weld While there, I observed well site with pumping unit.</p> <p><u>Weather conditions: sunny and dry</u> NO Follow up on site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p><u>This inspection does not nullify any orders or NOAV from the ECMC</u> This is a continuing education inspection</p>	kesterm	04/01/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300774	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490211