

Interim Reclamation and Stormwater Inspection

Date: 03/19/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP
-47120

Location ID: 333269

Inspection Document #: 708201011

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Zeiler 65N67W
Location ID: 333269



Photos 1 & 2. Taken near the location entrance and access road intersection. Access road requires maintenance as it is beginning to rut which can contribute to vehicle track out.



Photo 3. Erosion degradation (e.g. riling) occurring on the north side of the tank battery.

Inspection Photos
Location Name: Zeiler 65N67W
Location ID: 333269



Photo 4. Erosion degradation (e.g. riling) occurring near one of the northern sediment traps. Sediment trap appears to have been recently replaced or had repairs.

Inspection Photos
Location Name: Zeiler 65N67W
Location ID: 333269



Photo 5. Erosion degradation occurring on the northwest portion of the location.

Inspection Photos
Location Name: Zeiler 65N67W
Location ID: 333269



Photo 6. Continued from Photo 5, facing east.

Inspection Photos
Location Name: Zeiler 65N67W
Location ID: 333269



Photo 7. Stormwater control measure/BMPs requires maintenance as stormwater is beginning to undercut the velocity check/structure.