



**Location**

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Rule 606.: Trash, debris. Within the designated setback		
Corrective Action:	remove trash and debris. Rule 606. Corrective Action Date 4/19/2024. See attached photo #4	Date:	04/19/2024

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Count	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 4				
Type: Bird Protectors	# 4				
Type: Bradenhead	# 1				
Type: Pump Jack	# 1				
Type: Gas Meter Run	# 1				
Type: Horizontal Heated Separator	# 1				
Type: Ancillary equipment	# 1				
Type: Emission Control Device	# 3				

Corrective Action:	Date:
--------------------	-------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	CONCRETE SUMP/VAULT		

Comment:	Date:
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Date:
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.936948,-104.582181

Comment:	Date:
Corrective Action:	Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Date:
Corrective Action:	Date:

**Wells Served By Facilities Above**

API Number
001-07352

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 201948 Type: WELL API Number: 001-07352 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Appeared to be plumbed to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Friday, March 22nd, 2024 at approximately 10:55am. I, Inspector Chane Finkenbinder, conducted an on-site inspection.                      Operator: KP KAUFMANN                      Location name: UPRR 23 PAN AM D #2                      API #001-07352                      Location ID #: 319939                      County: Adams                      While there, I observed a Producing well.                      During this inspection the following possible compliance issues were observed:                      Rule 606.: Trash, debris. Within the designated setback, remove trash and debris. Rule 606. Corrective Action Date 4/19/2024. See attached photo #4                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	04/01/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700902029	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6491639">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6491639</a>