

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/28/2024

Submitted Date:

04/02/2024

Document Number:

708903433

**FIELD INSPECTION FORM**

Loc ID 335073 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

34 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263280	WELL	PR	09/27/2002	GW	045-08117	PA 324-26	PR
278146	WELL	PR	12/01/2010	GW	045-10839	PA 314-26	PR
279374	WELL	PR	03/01/2020	GW	045-11022	PA 414-26	PR
279375	WELL	PR	12/01/2018	GW	045-11023	PA 424-26	PR
279376	WELL	PR	08/16/2005	GW	045-11024	PA 524-26	PR
279377	WELL	PR	08/16/2005	GW	045-11025	PA 624-26	PR
279379	WELL	PR	06/14/2006	GW	045-11027	PA 321-35	PR
279459	WELL	PR	08/19/2005	GW	045-11040	PA 13-26	PR
279460	WELL	PR	08/19/2005	GW	045-11041	PA 313-26	PR
279461	WELL	PR	06/01/2006	GW	045-11042	PA 513-26	PR
279462	WELL	PR	12/01/2010	GW	045-11043	PA 413-26	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 03/28/2024 at approximately 12:54 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC PA324-26 Pad. Location # 335073 in Garfield County Colorado.  
Please refer to inspection 707800493 conducted on 07/20/2023, previous corrective actions have been completed.  
Location is within High Priority/Density Habitat areas.  
While there, I observed normal production operations.  
  
This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	300 bbl condensate tank label weathered & cracking but still legible at this time.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Type	OTHER		
Comment:	Small amount of stained soils & gravel near 2 wellheads		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Cataflow - hog panels		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Hog panels</a>		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	<a href="#">Hog panels</a>		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	<a href="#">Hog panels</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Cataflow</a>		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:	<a href="#">All wells on plunger lift</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Liquid nitrogen tank</a>		
Corrective Action:		Date:	
Type: Bradenhead	# 11		
Comment:	<a href="#">No form of pressure monitoring equipment located on bradenheads. All bradenhead valves are accessible.</a>		
Corrective Action:		Date:	
Type: Gas Meter Run	# 11		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:	<a href="#">Marked</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	<a href="#">Tank equipped with telemetry</a>				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: Centralized containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment: Centralized containment				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>263280</u>	Type:	<u>WELL</u>	API Number:	<u>045-08117</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>278146</u>	Type:	<u>WELL</u>	API Number:	<u>045-10839</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>279374</u>	Type:	<u>WELL</u>	API Number:	<u>045-11022</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>279375</u>	Type:	<u>WELL</u>	API Number:	<u>045-11023</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>279376</u>	Type:	<u>WELL</u>	API Number:	<u>045-11024</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>279377</u>	Type:	<u>WELL</u>	API Number:	<u>045-11025</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>279379</u>	Type:	<u>WELL</u>	API Number:	<u>045-11027</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					
Facility ID:	<u>279459</u>	Type:	<u>WELL</u>	API Number:	<u>045-11040</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Producing, well on plunger lift</u>								
Corrective Action:				Date:					

Facility ID: <u>279460</u>	Type: <u>WELL</u>	API Number: <u>045-11041</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment:	<u>Producing, well on plunger lift</u>			
Corrective Action:			Date:	
Facility ID: <u>279461</u>	Type: <u>WELL</u>	API Number: <u>045-11042</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment:	<u>Producing, well on plunger lift</u>			
Corrective Action:			Date:	
Facility ID: <u>279462</u>	Type: <u>WELL</u>	API Number: <u>045-11043</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment:	<u>Producing, well on plunger lift</u>			
Corrective Action:			Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						
		Gravel				Sparse to none in sections
Hydro Mulch						
Sediment Traps						
		Culverts				
		Ditches				
Compaction						Light compaction in small areas
Ditches						
Gravel						Sparse to none in areas
		Compaction				

Comment: Small amount of erosion developing behind production units.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903434	Inspection 708903433 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492114">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492114</a>
708903435	Inspection 708903433 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492115">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492115</a>