

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3ESE
Location ID: 335796



When replaced additional information is required

Erosion and sediment migration

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Sediment migration



Sediment migration

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3ESE
Location ID: 335796



Unmarked anchor




Unused equipment

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Unused equipment



Unused equipment

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Debris



Soil staining

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3ESE
Location ID: 335796



Soil staining



Unmarked anchor

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Unmarked anchor



Unmarked anchor

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3ESE
Location ID: 335796



Unmarked anchor



Unused equipment

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3ESE
Location ID: 335796



Unmarked anchor




Debris

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3ESE
Location ID: 335796



Debris



Relief risers missing rain protection

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3ESE
Location ID: 335796



Debris



Erosion and sediment migration

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Erosion and sediment migration



Erosion and sediment migration

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Production facility from Northeast corner



Production facility from Northwest corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Well pad from Northwest corner



Well pad from Southwest corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 3SESE
Location ID: 335796



Apr 2, 2024 at 4:39:36 PM



Apr 2, 2024 at 4:44:42 PM

Well pad from Southeast corner

Well pad from Northeast corner