

Inspection Photos
Location Name: CAERUS PICEANCE LLC RJ2 Pad
Location #: 334698



Photo # 2233 From entrance to location



Photo # 2234 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC RJ2 Pad
Location #: 334698



Photo # 2235 Location

Photo # 2236 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC RJ2 Pad
Location #: 334698



Photo # 2237 Location



Photo # 2238 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC RJ2 Pad
Location #: 334698



Photo # 2239 Hole in liner/liner needs maintenance



Photo # 2240 Hole in liner/liner needs maintenance & liner showing signs of deterioration

Inspection Photos
Location Name: CAERUS PICEANCE LLC RJ2 Pad
Location #: 334698



Photo # 2241 Holes in liner/liner needs maintenance

Photo # 2242 Holes in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC RJ2 Pad
Location #: 334698



Photo # 2243 Holes in liner/liner needs maintenance

Photo # 2244 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC RJ2 Pad

Location #: 334698



Photo # 2245 Hole in liner/liner needs maintenance



Photo # 2246 Hole in liner/liner needs maintenance & liner showing signs of deterioration