

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2024

Submitted Date:

04/03/2024

Document Number:

708903445

FIELD INSPECTION FORM

Loc ID 335270 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211158	WELL	PR	08/23/1995	GW	045-06917	VASSAR-HEATH RMV 21-28	PR
274938	WELL	PR	05/20/2005	GW	045-13444	WEBSTER HILL/HEATH RWF 532-28	PR

General Comment:

CECMC Inspection Report Summary
On 04/02/2024 at approximately 11:03 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC VASSAR-HEATH RMV21-28 Pad. Location # 335270 in Garfield County Colorado.
Location is within High Priority/Density Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost site. While there, I observed normal production operations.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	<input type="text" value="911/970-285-9377"/>	
Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 7		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:	Wells on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Pressure transducers & Taylor plugs located on bradenheads, bradenhead valves are accessible. VASSAR-HEATH RMV 21-28 well bradenhead tied into flowline - document # 402775818		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 211158 Type: WELL API Number: 045-06917 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

Facility ID: 274938 Type: WELL API Number: 045-13444 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in sections
Gravel						Sparse to none
		Ditches				
		Rip Rap				
Compaction						Large amount of light compaction
		Culverts				
		Compaction				Light compaction in sections

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Remote location/Split pad - Wellheads only - Separator units & tank battery located on the RMV 234-28 pad, location # 324164	smelserw	04/03/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903446	Inspection 708903445 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6494330
708903447	Inspection 708903445 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6494331