

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2024

Submitted Date:

04/04/2024

Document Number:

698706165**FIELD INSPECTION FORM**Loc ID 322888 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
,		randy.silver@state.co.us	
, /		Inspections@civiresources.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449620	WELL	PR	07/01/2022	OW	123-44414	VT-LDS C4-16-18	PR
449621	WELL	PR	10/24/2019	OW	123-44415	VT-Alles 1-16-18	PR

General Comment:[Updated Complaint Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	2	400 BBLs	STEEL AST			
Comment: Shares containment with crude oil tanks						
Corrective Action:						Date:
<u>Paint</u>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	8	400 BBLs	STEEL AST		40.402500,104.652564	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities			
Facility ID: 449620	Type: WELL	API Number: 123-44414	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 03/09/2023		Annual Brhd Completed? _____	
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type: _____	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
Facility ID: 449621	Type: WELL	API Number: 123-44415	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 10/12/2023		Annual Brhd Completed? Yes	
Last Brhd Test Results	Initial Surf Csg Pressure: 198	Fluid Type: NONE	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
COGCC Comments			
Comment	User	Date	
RE-Inspection to Complaint ECMC Inspection Report Summary On 4/4/24 at approximately 12:00pm, I, Inspector Abe Serna, conducted an on-site inspection. Location: Alles 1-16-18 Tank Battery Operator: Civitas API#: 123-44415 County: Weld While there, I observed a PR Well During this inspection no possible compliance issues were observed: Weather conditions: Sonny I spoke with Jeremy Martinez , he said a PRV Valve was going to be removed & cleaned then replaced also an employee was dragging a sand screen to level location road from holes & a crew were testing flow line as part of an annual test. At time of inspection there was no sign of venting or leaking gas. No follow up on this site inspection needs to be conducted. This is a summary of inspection report. Any corrective actions from previous inspections that have not been addressed are still applicable	sernaa	04/04/2024	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698706166	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6496068