

Inspection Photos

Loc: 485654

Operator: BNL (ENTERPRISE) INC

Inspection Date: 4/2/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the access road. The sides of the road will need to be reclaimed. The road is not crowned and there are no ditches for stormwater which may become a problem. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 4/2/2024

Inspection Photos



Photo 2. The drainage crossing has a large culvert but there is no outlet protection and loose gravel is falling into the culvert. Previous corrective action was not completed.



Photo 3. The embankment along the road side at the culvert is not stabilized and loose gravel is falling into the culvert.



Inspection Photos



Photo 3. Facing northwest toward the access road. The side of the road needs to be seeded and stabilized and the road needs to be crowned and graveled. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 4/2/2024

Inspection Photos



Photo 4. Facing northwest toward the location. Sign posted at entrance.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 4/2/2024

Inspection Photos



Photo 5. Facing toward the drilled well. The drill cuttings have been removed.



Inspection Photos



Photo 6. Facing west at the corner of the location. Unused areas of the location will need to be recontoured and reclaimed with 6 moths of drilling.



Inspection Photos



Photo 7. There are several areas where the silt fence is not maintained. Previous corrective was not completed.



Inspection Photos



Photo 8. Facing toward the soil stock pile. The stock pile will need to be seeded before the growing season unless it will be re-spread for reclamation before that time.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 4/2/2024

Inspection Photos



Photo 9. Facing east at the corner of the location. Unused areas of the location will need to be recontoured and reclaimed with 6 months of drilling.



Inspection Photos



Photo 10 There are several area where the silt fence is not maintained. Previous corrective action was not completed.

