

Inspection Photos

Operator: ENDURING RESOURCES LLC -10663

Location Name: STATE #36-6 API #:05-067-09452


Location Name: STATE #36-5 API #:05-067-08400

Location ID:334422

Inspection Date:4/3/2024 Inspection Doc#: 693807028



Injection wellhead during MIT
STATE #36-6 API #:05-067-09452



Form 21 field copy
STATE #36-6 API #:05-067-09452

Inspection Photos

Operator: ENDURING RESOURCES LLC -10663

Location Name: STATE #36-6 API #:05-067-09452

Location Name: STATE #36-5 API #:05-067-08400

Location ID:334422

Inspection Date:4/3/2024 Inspection Doc#: 693807028



**Location entrance with sign
Gas meter and flowline fencing.
Separator and tank battery removed**



**Wellhead with pump jack
STATE #36-5 API #:05-067-08400**