

Inspection Photos on 4/2/24
Operator: Phoenix Resources
Location Name: Mosher 1-1H
API: 05-073-06393



Looking north from entrance at cattle guard



Concrete blocks and debris laying around

On April 2nd 2024, the Compliance Specialist observed that the corrective actions from the previous inspection on 9/21/23 (Doc #701007374) were not completed

Inspection #715200028

Inspection Photos on 4/2/24
Operator: Phoenix Resources
Location Name: Mosher 1-1H
API: 05-073-06393



Brian Welch SE Field Inspector COGCC
38 93861, -103 38835, 4804 2H
04/02/2024 09:44:28

NW corner of location looking south



Brian Welch SE Field Inspector COGCC
38 93831, -103 3872, 4765 1H
04/02/2024 09:56:49

NE corner of location looking SW

On April 2nd 2024, the Compliance Specialist observed that the corrective actions from the previous inspection on 9/21/23 (Doc #701007374) were not completed

Inspection #715200028

Inspection Photos on 4/2/24
Operator: Phoenix Resources
Location Name: Mosher 1-1H
API: 05-073-06393



Brian Welsh SE Field Inspector COGCC
38-93815, 103-3883, 4795-711
04/02/2024 10:00:13

SE corner of tank berms



Brian Welsh SE Field Inspector COGCC
38-93815, 103-3883, 4795-711
04/02/2024 10:02:02

North side of tank battery

On April 2nd 2024, the Compliance Specialist observed that the corrective actions from the previous inspection on 9/21/23 (Doc #701007374) were not completed

Inspection #715200028

Inspection Photos on 4/2/24
Operator: Phoenix Resources
Location Name: Mosher 1-1H
API: 05-073-06393



Brian Welsh SE Field Inspector COGCC
38.93787, -103.38798, 4802.8ft
04/02/2024 10:01:28

Old metal berms on south side of existing battery



Brian Welsh SE Field Inspector COGCC
38.93798, -103.38806, 4811.4ft
04/02/2024 10:05:42

Picture showing how bad tanks are rotting

On April 2nd 2024, the Compliance Specialist observed that the corrective actions from the previous inspection on 9/21/23 (Doc #701007374) were not completed

Inspection #715200028