

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 4/4/2024



Location Entrance – Photo #00365



Wellheads – Photo #00367

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 4/4/2024



Separators – Photo #00369



Tank Battery – Photo #00366

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 4/4/2024



Open-Ended Load Line – Photo #00370



Open-Ended Load Line – Photo #00371

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 4/4/2024



Open-Ended Load Line – Photo #00373



Debris in Containment – Photo #00374



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 4/4/2024



Lack of Stabilization – Photo #00375



Lack of Stabilization – Photo #00376

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/34-5

Location ID: 334816

Date: 4/4/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00377