

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 4/4/2024



Wellheads – Photo #00379



Separators – Photo #00382

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 4/4/2024



Tank Battery – Photo #00383



Heater Treaters – Photo #00387

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 4/4/2024



Damaged Fencing – Photo #00385

Damaged Fencing – Photo #00386

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 4/4/2024



Open-Ended Vent/Wildlife Entry Hazard – Photo #00384



Lack of Stabilization – Photo #00380

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 4/4/2024



Lack of Stabilization – Photo #00381



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00388**