

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2616 From entrance to location



Photo # 2617 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2618 Location



Photo # 2619 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2620 Location



Photo # 2621 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2622 Location



Photo # 2623 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2624 Location



Photo # 2625 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2626 Location



Photo # 2627 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2628 Location



Photo # 2629 Tank missing required information & some information is illegible

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2630 Tank missing required information



Photo # 2631 Tank missing required information & some information is illegible

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2632 Tank missing required information & some information is illegible



Photo # 2633



Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2634 Tank missing required information & some information is illegible



Photo # 2635

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2636 Tank missing required information & some information is illegible



Photo # 2637 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Apr 3, 2024 at 1:21:23 PM
CO



Apr 3, 2024 at 1:21:35 PM
CO

Photo # 2638 Tank missing required information & some information is illegible

Photo # 2639 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2640 Storage tank on compressor skid lacks required labeling



Photo # 2641 Storage tank on compressor skid lacks required labeling

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2642 Storage tank on compressor skid lacks required labeling



Photo # 2643 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2644 Stained soils & gravel



Photo # 2645 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2646 Stained soils & gravel



Photo # 2647 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2648 Stained soils & gravel



Photo # 2649 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2650 Stained soils & gravel



Photo # 2651 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2652 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 2653 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2654 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 2655 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2656 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 2657 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2658 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 2659 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2660 Tank label damaged & becoming illegible



Photo # 2661 Production tank lacks some required info

Inspection Photos

Location Name: CAERUS PICEANCE LLC Rulison Compressor Station

Location # 466236



Photo # 2662 Tank battery lacks required signage



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources