

Inspected Facilities

Facility ID: 297627 Type: WELL API Number: 123-28014 Status: PA Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [ECMC Environmental Inspection Remediation Project 30762 for well plugging, cut & cap and Rule 911 assessment. ECMC notes cut and cap date of 10/25/2023 on approved Form 6-S Document #403593361. Well site is backfilled. ECMC expected a Supplemental Form 27 with well assessment results by 1/23/2024. No Supplemental Form 27 has been received.](#)
[ECMC notes flowline was abandoned prior to January 15, 2024 according to Initial Form 27 Document #403465209.](#)

Corrective Action: [Submit a Supplemental Form 27 with well assessment results.](#) Date: 04/29/2024

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403737572	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488808
693701142	Shable14-22wellsite3-22-2024(2)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488799
693701143	Shable14-22wellsite3-22-2024(1)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488800