

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2024

Submitted Date:

03/29/2024

Document Number:

693701149

FIELD INSPECTION FORMLoc ID 417954 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Environmental		rbuef27@chevron.com	
, Inspections		rbucogccinspectionreports@chevron.com	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Peterson, Dan		danpeterson@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417949	WELL	SI	06/01/2017	OW	123-31799	SHABLE USX AB11-11P	EI

General Comment:

Inspected Facilities									
Facility ID:	417949	Type:	WELL	API Number:	123-31799	Status:	SI	Insp. Status:	EI

--

Environmental

Spill/Remediation:

Comment:

ECMC Environmental Inspection Remediation Project 30810 for well plugging, cut & cap and Rule 911 assessment. Well site is backfilled.

Operator reported a historical release associated with the well flowline on 1/19/2024 via email and Initial Form 19 Document #403660384. The Form 19 latitude/longitude indicated a Release at the flowline point at the well site, but included data indicated a release within the flowline corridor and was unclear which Release Form 19 was meant to document. ECMC returned Form 19 Document #403660384 to Draft status on 1/23/2024 for clarifications regarding exact spill location(s). Form 19 Document #403660384 has not been resubmitted.

ECMC received a Supplemental Form 27 Document #403660099 on 1/19/2024 that appeared intended to address the Spill at the flowline. ECMC returned Form 27 Document #403660099 to draft status on 1/23/2024. Operator resubmitted Form 27 on 1/26/2024, and ECMC approved the Form 27 on 3/29/2024 approving consolidation of flowline release point onto Remediation Project 30814.

This Form 27 does not include well assessment results. Form 6 Document # 403621199 indicated well was cut and capped 11/9/2023.

Corrective Action:

Operator shall submit well assessment data within 30 days (April 28, 2024) on a Supplemental Form 27.

Resubmit the Initial Form 19 addressing the requested corrections for the flowline release if applicable, or submit FIRR documenting Form 19 would be duplicative of Form 29 Document #403660755, if appropriate. This release potentially remains undocumented by the Form 19.

Date:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403737582	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488811