



Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue no prime mover on pumpjack		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>03/14/2024</u>
Type	UNUSED EQUIPMENT		
Comment:	Pumpjack has no motor to operate needs to be removed		
Corrective Action:	Comply with rule 606		Date: <u>03/14/2024</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:			Date:
Type	OTHER		
Comment:	electric/automation disconnect, metal panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover #			corrective date
Comment:	Removed, disassembled		
Corrective Action:			Date:
Type: Ancillary equipment # 3			
Comment:	automation/electric panels		
Corrective Action:			Date:
Type: Pump Jack # 1			

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241253 Type: WELL API Number: 123-09041 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTED

Comment: Valves appeared to be closed at time of inspection

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      Inspector Michael Kester,                      conducted Follow up on-site inspection as per Doc 698705903 corrective actions have not been addressed.                      Location: UPRR 43 PanAm I 21                      Operator: KPK                      API#: 123-09041                      County: Weld                      While there, I observed well site with pumping unit,                      During this inspection, the following possible compliance issues were observed:                      Unused equipment, Rule 606, corrective action date 3-14-2024                      Mechanical Issues, Rule 608e, corrective action date 3-14-2024                      Weather conditions: sunny and dry                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC                      This is a continuing education inspection</p>	kesterm	04/01/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403738740	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490215">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490215</a>
713300772	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490210</a>