

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2024

Submitted Date:

04/09/2024

Document Number:

705000659

**FIELD INSPECTION FORM**

Loc ID 305798 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282456	WELL	SI	12/01/2020	OW	123-23494	MCHALE 2-5	PA
305798	LOCATION	AC			-	MCHALE-62N67W 5NWNE	EG

**General Comment:**

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 282456 Type: WELL API Number: 123-23494 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 305798 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403739881 received on 04/03/2024: On April 2, 2024, historically impacted soil was discovered following cut and cap operations at the wellhead and flowline riser removal activities at the McHale 2-5 wellhead location.. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	04/09/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000660	Signage on location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501697</a>
705000661	Fenced excavation at PA well; No OLF Riser	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501698">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501698</a>