

Caerus
F17
Location ID: 335023



Location



Location

Caerus
F17
Location ID: 335023



Location



Fencing is falling down

Caerus
F17
Location ID: 335023



Fencing is falling down



Fencing is falling down

Caerus
F17
Location ID: 335023



Fencing is falling down



Lack of stabilization/compaction

Caerus
F17
Location ID: 335023



Lack of stabilization/compaction



Lack of stabilization/compaction

Caerus
F17
Location ID: 335023



Lack of stabilization/compaction



Lack of stabilization/compaction

Caerus
F17
Location ID: 335023



Fencing is falling down



Lack of stabilization/compaction

**Caerus
F17
Location ID: 335023**



Some areas of cut slope show signs of erosion