

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2024

Submitted Date:

04/09/2024

Document Number:

699108494

FIELD INSPECTION FORM

Loc ID 332724 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296711	WELL	TA	08/01/2019	GW	123-26873	CONAGRA B 30-23XD	PA

General Comment:

[Routine Well Inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Panel fence needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	04/19/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 296711 Type: WELL API Number: 123-26873 Status: TA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: P/A
Well was cut and capped on 1/22/24
Form 27(S) in process
Form 6(S) in process

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday, April 9, 2024, at approximately 8:32am, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Location: Conagra B 30-23X Operator: Chevron API # 05-123-26873 County: Weld</p> <p>During the inspection, a P/A well was observed. The following possible compliance issues were identified:</p> <p>Unused Panel Fence: Unused Panel fence needs to be removed for good housekeeping. Comply with Rule 606. Corrective Action deadline: April 19, 2024.</p> <p>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Attached are photos, an annotation report, and an issues report.</p> <p>Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	04/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699108495	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501835