

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2024

Submitted Date:

04/09/2024

Document Number:

702403325**FIELD INSPECTION FORM**Loc ID 330771 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| ,            |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 251792      | WELL | SI     | 02/01/2021  | GW         | 123-19596 | ARROWHEAD FARMS 7-22A | SI          |

**General Comment:**[This is a wellsite inspection.](#)

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | adequate |       |  |
| Corrective Action:   |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Ag Panel |       |  |
| Corrective Action: |          | Date: |  |

|                           |                              |       |                 |
|---------------------------|------------------------------|-------|-----------------|
| <b>Equipment:</b>         |                              |       | corrective date |
| Type: Bradenhead          | # 1                          |       |                 |
| Comment:                  | exposed at surface           |       |                 |
| Corrective Action:        |                              | Date: |                 |
| Type: Other               | # 1                          |       |                 |
| Comment:                  | Fugitive gas recovery device |       |                 |
| Corrective Action:        |                              | Date: |                 |
| Type: Ancillary equipment | # 1                          |       |                 |
| Comment:                  | Automation                   |       |                 |
| Corrective Action:        |                              | Date: |                 |
| Type: Plunger Lift        | # 1                          |       |                 |
| Comment:                  |                              |       |                 |
| Corrective Action:        |                              | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|          |  |  |
|----------|--|--|
| Type     |  |  |
| Comment: |  |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

Inspected Facilities

Facility ID: 251792

Type: WELL

API Number: 123-19596

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder:

Comment: SI, LOTO and is on the inactive list. Form 06A Doc # 403108165.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/07/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 1

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: exposed at surface.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Date Run: 4/9/2024 Doc [#702403325]

Page 4 of 5

Reclamation - Storm Water - Pit

Storm Water:

|  |                 |                         |                       |               |                          |                            |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------|
| Loc Erosion BMPs   | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment                    |
|  |                 |                         |                       |               |                          |                            |
| Comment: <input type="text"/>  |                 |                         |                       |               |                          | Date: <input type="text"/> |
| Corrective Action: <input type="text"/>                                |                 |                         |                       |               |                          |                            |
| Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT |                 |                         |                       |               |                          |                            |

ECMC Comments

| Comment  | User   | Date       |
|--|--------|------------|
| This is a Routine Field Inspection. Any Corrective Actions from previous inspections not addressed are still applicable. | revasr | 04/09/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description     | URL   |
|--------------|-----------------|---|
| 702403326    | Location photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501971">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501971</a> |