

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/02/2024

Submitted Date:

04/02/2024

Document Number:

699505667

**FIELD INSPECTION FORM**Loc ID 441273 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451804	WELL	PR	04/01/2023	OW	123-45246	ROBIN 9-18HZ	PR
451805	WELL	PR	02/16/2019	OW	123-45247	ROBIN 9-15HZ	PR
451806	WELL	PR	05/01/2023	OW	123-45248	ROBIN 9-14HZ	PR
451807	WELL	PR	06/01/2022	OW	123-45249	ROBIN 9-17HZ	PR
451808	WELL	SI	10/01/2022	OW	123-45250	ROBIN 9-16HZ	SI
451809	WELL	PR	02/20/2019	OW	123-45251	ROBIN 9-13HZ	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Pump Jack # 3

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 2

Comment:

Corrective Action:

Date:

Type: Prime Mover # 3

Comment: electric motor

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: electric / automation

Corrective Action:

Date:

Type: Bradenhead # 6

Comment: Plumbed to surface

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 451804	Type: WELL	API Number: 123-45246	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451805	Type: WELL	API Number: 123-45247	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451806	Type: WELL	API Number: 123-45248	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451807	Type: WELL	API Number: 123-45249	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451808	Type: WELL	API Number: 123-45250	Status: SI	Insp. Status: SI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 451809	Type: WELL	API Number: 123-45251	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 03/07/2023

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 17

Fluid Type: GAS

End Surf Csg Pressure: 1

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment

User

Date

At time of inspection location appears to be in compliance with ECMC rules.  
At time of inspection weather conditions were cold, some clouds, light wind.

medinaj

04/02/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505668	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501960">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6501960</a>