

Interim Reclamation and Stormwater Inspection

Date: 4/4/24

Operator: Highpoint Operating Corporation - 10071

Location ID: 444730

Inspection Document #: 713900523

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20_21 NWNW

Location ID: 444730



Photo 1. The photo was taken at the well location facing Southeast. The photo illustrates the production pad.

Photo 2. The photo was taken at the well location facing South. The photo illustrates the marked topsoil stockpile with good germination of perennial vegetation.

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20_21 NWNW

Location ID: 444730



Photo 3. The photo was taken at the well location facing South. The photo illustrates the interim area on the West side of the location has been mowed.

Photo 4. The photo was taken at the well location facing Northeast. The photo illustrates the berm around the edge of the production pad.

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20_21 NWNW

Location ID: 444730



Photo 5. The photo was taken at the well location facing West. The photo illustrates unmarked risers at the location.



Photo 6. The photo was taken at the well location facing West. The photo illustrates the Northern interim area has been mowed.

Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20_21 NWNW

Location ID: 444730



Photo 7. The reference photo was taken at the edge of the location facing Northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 713900523