

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3210 From entrance to location




Photo # 3211 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3212 Location



Photo # 3213 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Apr 9, 2024 at 9:54:34 AM
CO

Photo # 3214 Location



Apr 9, 2024 at 9:56:31 AM
CO

Photo # 3215 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3216 Location



Photo # 3217 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3218 Stored farm equipment on location



Photo # 3219 Stored farm equipment on location

Inspection Photos
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3220 Open ended piping on separator/wildlife hazard/available for entry by wildlife



Photo # 3221 Open ended piping on separator/wildlife hazard/available for entry by wildlife

Inspection Photos
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3222 Open ended piping on separator/wildlife hazard/available for entry by wildlife



Photo # 3223 Open ended piping on separator/wildlife hazard/available for entry by wildlife

Inspection Photos
Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad
Location ID: 334653



Photo # 3224 Open ended piping on separator/wildlife hazard/available for entry by wildlife




Photo # 3225 Open ended piping on separator/wildlife hazard/available for entry by wildlife



Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3226 Open ended piping on separator/wildlife hazard/available for entry by wildlife



Photo # 3227 Open ended piping on separator/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3228 Open ended piping on separator/wildlife hazard/available for entry by wildlife



Photo # 3229 Open ended piping on separator/wildlife hazard/available for entry by wildlife



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3230 Open ended piping/wildlife hazard/available for entry by wildlife




Photo # 3231 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3232 Barbed wire fence needs maintenance



Photo # 3233 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3234 Barbed wire fence needs maintenance/wildlife hazard



Photo # 3235 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3236 Barbed wire fence needs maintenance/wildlife hazard



Photo # 3237 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3238 Barbed wire fence needs maintenance/wildlife hazard



Photo # 3239 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC CLEM JR. (PB-15) Pad

Location ID: 334653



Photo # 3240 Hole/wildlife & personnel hazard