

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2024

Submitted Date:

04/09/2024

Document Number:

702502566

FIELD INSPECTION FORM

Loc ID 315097 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10654
Name of Operator: LASSO OIL & GAS LLC
Address: 3021 RIDGE RD #156
City: ROCKWALL State: TX Zip: 75032

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107194	PIT		09/23/1999		-	CONTINENTAL 1-8	
230249	WELL	PR	03/01/2019	GW	103-07908	CONTINENTAL 1-8 (OWP)	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday, 04/09/2024, Inspector Kirby Burchett, conducted a routine field inspection at Lasso Oil & Gas LLC on the Continental 1-8 (OWP) well, Location #315097, in Rio Blanco County, Colorado.

Orphan Well Program. Field inspection only.

No follow up inspection is required.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:	Livestock wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Rails		
Corrective Action:		Date:	

Equipment:

Type	Equipment	Quantity	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked		# 2				
Comment:						
Corrective Action:					Date:	
Type: Other		# 1				
Comment:	Wellhead					
Corrective Action:					Date:	
Type: Gas Meter Run		# 1				
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:

Date:

Inspected Facilities

Facility ID: 107194 Type: PIT API Number: - Status: _____ Insp. Status: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 230249 Type: WELL API Number: 103-07908 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Orphan Well Program

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: 107194 Lat: 39.807211 Long: -108.648786

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
702502567	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6502253