

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/29/2024

Submitted Date:

04/03/2024

Document Number:

697602312

FIELD INSPECTION FORM

Loc ID 454886 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454884	WELL	PR	01/18/2019	OW	123-46761	Hurley H26-743	EI
454885	WELL	SI	02/01/2023	OW	123-46762	Hurley H26-736	EI
454887	WELL	PR	01/19/2019	OW	123-46763	Hurley H26-730	EI
454891	WELL	PR	01/21/2019	OW	123-46765	Hurley H26-717	EI
454895	WELL	PR	01/22/2019	OW	123-46769	Hurley H26-724	EI
454896	WELL	SI	09/01/2023	OW	123-46770	Hurley H26-712	EI
454951	WELL	PR	05/06/2020	OW	123-46808	Hurley H35-727	EI
454952	WELL	PR	01/03/2022	OW	123-46809	Hurley State H35-713	EI
454953	WELL	PR	01/03/2022	OW	123-46810	Hurley H35-733	EI
454954	WELL	PR	05/10/2020	OW	123-46811	Hurley H35-746	EI
454955	WELL	AL	06/18/2019	LO	123-46812	Hurley H35-719	EI
454956	WELL	AL	06/18/2019	LO	123-46813	Hurley H35-740	EI

General Comment:

This is an environmental inspection for Facility ID 454886. Any corrective actions from previous inspections that have not been addressed are still applicable. Operator personnel was on location installing piping for a potential gas lift at the time of this field inspection. Photos attached to document site conditions.

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:		All signage at the wellheads were adequate.		
Corrective Action:		Date:		
Good Housekeeping:				
Type	OTHER			
Comment:		Extra fencing posts and other debris were left onsite		
Corrective Action:		Compy with houekkeeping Rule 606.		Date: 04/10/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:		All metal fencing was adequate.		
Corrective Action:		Date:		
Venting:				
Yes/No				
Comment:				
Corrective Action:		Date:		
Flaring:				
Type				
Comment:				
Corrective Action:		Date:		

Inspected Facilities

Facility ID: 454884	Type: WELL	API Number: 123-46761	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454885	Type: WELL	API Number: 123-46762	Status: SI	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454887	Type: WELL	API Number: 123-46763	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454891	Type: WELL	API Number: 123-46765	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454895	Type: WELL	API Number: 123-46769	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454896	Type: WELL	API Number: 123-46770	Status: SI	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454951	Type: WELL	API Number: 123-46808	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454952	Type: WELL	API Number: 123-46809	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454953	Type: WELL	API Number: 123-46810	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454954	Type: WELL	API Number: 123-46811	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454955	Type: WELL	API Number: 123-46812	Status: AL	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 454956	Type: WELL	API Number: 123-46813	Status: AL	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403741367	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6493255
697602313	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6493252