

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2024

Submitted Date:

04/03/2024

Document Number:

699108472

FIELD INSPECTION FORMLoc ID 451280 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451280	LOCATION	AC			-	Bath-Schmier 5N64W32 1-11	AC

General Comment:[This is an inspection on the tank battery.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil next to the lact unit needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	04/19/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Separator	# 1		
Comment:	Bulk Separator		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	air compressor		
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment: Air storage vessel		Date:
Corrective Action:		Date:
Type: Emission Control Device	# 13	
Comment:		
Corrective Action:		Date:
Type: Other	#	
Comment: Multiple Unmarked risers need to be marked by identifying what they are and tagged with OOSLAT. "LOTO". See attached photos		
Corrective Action: Comply with the 1100 rules		Date: 04/19/2024
Type: Horizontal Heated Separator	# 12	
Comment:		
Corrective Action:		Date:
Type: VRU	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 12	
Comment: 2 Sheds		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	

Other (Capacity) 210 BBLs						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	11	OTHER	STEEL AST		40.353400,-104.582400	
Comment:						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 538 BBLs						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
Flaring:						
Type						
Comment:						
Corrective Action:				Date:		

Inspected Facilities

Facility ID: 451280 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: Active tank battery

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary On Wednesday, April 3, 2024, at approximately 10:00 AM, Inspector Adam Burns conducted an on-site inspection at the following location: Location: Bath-Schmier 5N64W32 1-11 Tank Battery Operator: Chevron Location ID: 451280 County: Weld During the inspection, an active tank battery was observed. The following possible compliance issues were identified: Stained Soil: Stained soil next to the lact unit requires removal. Proper disposal of oily waste is necessary in accordance with 905.e. Corrective Action deadline: April 19, 2024. Unmarked Risers: Multiple unmarked risers need to be identified and tagged with OOSLAT, in compliance with LOTO rules outlined in the 1100 rules. Corrective Action deadline: April 19, 2024. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Attached are photos, an annotation report, and an issues report. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.	burnsa	04/03/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403741528	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6493417
699108473	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6493415