

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2024

Submitted Date:

04/09/2024

Document Number:

695109369

FIELD INSPECTION FORMLoc ID 333864 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259433	WELL	PR	10/06/2001	CBM	071-07249	MCCLAREN 13-34	PR
278564	WELL	PR	04/01/2013	CBM	071-08437	MCCLAREN 13-34TR	PR

General Comment:

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Progressive Cavity	# 1				
Comment:		ORIG WELL			
Corrective Action:				Date:	
Type: Deadman # & Marked	# 8				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 2				
Comment:		BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:				Date:	
Type: Bradenhead	# 2				
Comment:		BOTH ARE ACCESSABLE			
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:		TR WELL			
Corrective Action:				Date:	
Type: Vertical Separator	# 2				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:		ORIG. WELL			
Corrective Action:				Date:	
Type: Ancillary equipment	# 2				
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	259433	Type:	WELL	API Number:	071-07249	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	278564	Type:	WELL	API Number:	071-08437	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 262425Lat: 37.212701Long: -104.879111Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: PIT PERMIT FOR TR WELL IS NOT ON FILE, CONTACT AREA EPS TO RESOLVE.Corrective Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: Type: Produced WaterLined: NOPit ID: 262352Lat: 37.213213Long: -104.881246Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: NoneFencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date:

Inspector Name: Beardslee, Tom

Anchor Trench Present: <u>NO</u>	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective		
	Date:	

ECMC Comments		
Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695107864, CA HAS BEEN ADDRESSED. CONTACT AREA EPS TO RESOLVE TR PIT PERMIT ISSUE.	beardslt	04/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695109370	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6502703