

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 4/9/2024



Wellheads – Photo #00458



Separators – Photo #00463

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 4/9/2024



**Tank Battery – Photo #00468**



**Tank Label not Posted – Photo #00469**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 4/9/2024



**Debris – Photo #00460**



**Unprotected Soil Stockpile – Photo #00461**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 4/9/2024



**Unprotected Soil Stockpile – Photo #00462**



**Insufficient Erosion Control/Sediment Run-on to Location – Photo #00464**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 4/9/2024



**Sediment Run-on to Location/Lack of Stabilization – Photo #00465**

**Sediment Run-on to Location/Lack of Stabilization – Photo #00467**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 4/9/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #00470