

**Inspection Photos**  
**Location Name: Elaine 43-28**  
**Location ID: 336320**



**Photo 1 TB Location.**



**Photo 2 Horizontal heated Separator.**

Inspection Photos  
Location Name: Elaine 43-28  
Location ID: 336320



Photo 3 TB berm is over run with debris (dead vegetation).



Photo 4 TB sign.



Inspection Photos  
Location Name: Elaine 43-28  
Location ID: 336320



Photo 5 TB berm over run with debris (dead vegetation).



Photo 6 TB berm over run with debris (dead vegetation).



**Inspection Photos**  
**Location Name: Elaine 43-28**  
**Location ID: 336320**



**Photo 7 TB berm over run with debris (dead vegetation).**



**Photo 8 Well site location.**



Inspection Photos  
Location Name: Elaine 43-28  
Location ID: 336320



Photo 9 WH.



Photo 10 Pump jack base is over run with debris (dead vegetation)..



**Inspection Photos**  
**Location Name: Elaine 43-28**  
**Location ID: 336320**



**Photo 11 Dead vegetation/Stained soil by the prime mover (gas engine).**



**Photo 12 Pump jack base is over run with debris (dead vegetation)..**



Inspection Photos  
Location Name: Elaine 43-28  
Location ID: 336320



Photo 13 Dead vegetation around the WH sign



Photo 14 PJ base is over run with debris (dead vegetation) & the PJ gear box is leaking oil onto the ground.

**Inspection Photos**  
**Location Name: Elaine 43-28**  
**Location ID: 336320**



**Photo 15 PJ gear box is leaking oil onto the ground.**