

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
04/10/2024  
Submitted Date:  
04/10/2024  
Document Number:  
709200111

**FIELD INSPECTION FORM**

Loc ID 312147 Inspector Name: Abrams, Deborah On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10487  
Name of Operator: SPRINGDALE PARTNERS LLC  
Address: 3409 MONTECLAIRE DR  
City: SHERMAN State: TX Zip: 75092

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

1 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**General Comment:**

This is an orphaned well inspection. Inspection completed to document current condition of location, equipment, and wellhead. Inspection may also identify possible task required for final closure/release of location from the Orphaned Well Program. See link at end of report for path to downloadable documents and pictures.  
The tank battery is located 96' SE of the wellhead.  
The tank battery shares the same Location ID as the wellhead.  
670' of Flowlines E to the Compressor Station.  
Wellhead is fenced and in a cement cellar (6'L x 6.5'W x 1'D x 5" thick). No livestock observed.  
Location is fairly level and access road clear.

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709200112	FIR Photos PDF	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503635</a>
709200113	FIR Photos PPT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503636">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503636</a>
709200114	Tank in cement cellar	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503637">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503637</a>
709200115	Tank Battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503638">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503638</a>
709200116	Well head in cement cellar	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503639">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503639</a>
709200117	Tank Battery Sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503640">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503640</a>
709200118	Risers on Location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503641">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503641</a>
709200119	Incorrect sign at well head	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503642">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503642</a>