

# Construction and Stormwater Inspection

Date: 04/09/2024

Operator: PDC ENERGY INC - 69175

Location ID: 485098

Inspection Document #: 708201131

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Denali State 5N67W13 1-23  
Location ID: 485098



Photo 1. Form 2A posted at the location entrance.

Inspection Photos  
Location Name: Denali State 5N67W13 1-23  
Location ID: 485098



**Photo 2.** Vehicle track out pad installed along the access road.

## Inspection Photos

Location Name: Denali State 5N67W13 1-23

Location ID: 485098



**Photo 3.** Taken near the proposed well locations. Topsoil salvage operations had not commenced at the time of this inspection. The Operator shall ensure that all topsoil is salvaged for the location and access road, in compliance with Rule 1002.b.

## Inspection Photos

Location Name: Denali State 5N67W13 1-23

Location ID: 485098



**Photo 4.** Taken near the northeast corner of the disturbance area. Topsoil salvage operations had not commenced at the time of this inspection; onsite crews were in the process of installing a perimeter stormwater control BMP (ditch and berm). Additionally, silt fence has been installed along the northern portion of the disturbance area.



# Inspection Photos

Location Name: Denali State 5N67W13 1-23

Location ID: 485098



**Photo 5.** Taken near the northwest corner of the disturbance area. Topsoil salvage operations had not commenced at the time of this inspection; onsite crews were in the process of installing a perimeter stormwater control BMP (ditch and berm).

## Inspection Photos

Location Name: Denali State 5N67W13 1-23

Location ID: 485098



**Photo 6.** Taken near the southwest corner of the disturbance area. Topsoil salvage operations had not commenced at the time of this inspection; onsite crews were in the process of installing a perimeter stormwater control BMP (ditch and berm).

## Inspection Photos

Location Name: Denali State 5N67W13 1-23

Location ID: 485098



**Photo 7.** Taken near the southeast corner of the disturbance area. Topsoil salvage operations had not commenced at the time of this inspection; onsite crews were in the process of installing a perimeter stormwater control BMP (ditch and berm).