

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/11/2024

Document Number:

702403347

FIELD INSPECTION FORM

Loc ID 336183 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280696	WELL	PR	04/01/2023	GW	013-06519	OXFORD FARMS 31-26	PR
291196	WELL	PR	04/01/2023	GW	013-06552	OXFORD FARMS 32-26	PR

General Comment:

[This is a Multi-well inspection.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate x 2		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Ag panel x 2		
Corrective Action:		Date:	

Equipment:

Type	#	corrective date
Ancillary equipment	# 2	
Comment:	automation	
Corrective Action:		Date:
Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:
Bradenhead	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	See Inspection Doc # 702403345 for related shared facilities and equipment.				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 280696 Type: WELL API Number: 013-06519 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 291196 Type: WELL API Number: 013-06552 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/20/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
This is a Routine Field Inspection. Any Corrective Actions from previous inspections not addressed are still applicable.	revasr	04/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403348	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6505121