

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2024

Submitted Date:

04/11/2024

Document Number:

708903514

FIELD INSPECTION FORMLoc ID 322314 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|--------------------------|---------|
| , Mustang | | nwelch@vaqueroenergy.com | |
| Toews, Wesley | | wtoews@blm.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 210256 | WELL | PR | 10/01/2023 | GW | 045-06012 | RULISON FEDERAL 35-94-6S-94W | PR |

General Comment:**CECMC Inspection Report Summary**

On 04/11/2024 at approximately 13:21 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad.

Location # 322314 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.

Location is approximately 272 yards from Porcupine Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Unused equipment on location with a CA date of 05/11/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|-----------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | No tank battery | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 911/1-888-291-8588

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | DEBRIS | | |
| Comment: | Debris - please refer to photo log | | |
| Corrective Action: | | Date: | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment on location - extra meter house on location & equipment is not in use | | |
| Corrective Action: | The storage or placement of equipment and supplies not necessary for use on location is prohibited. | Date: | 05/11/2024 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|---------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 0 | | |
| Comment: | Well is not on plunger lift | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | 1 meter house is not hooked up & is not in use/unused equipment, please refer to Housekeeping for CA | | |

| | | | |
|------------------------|----|-------|--|
| Corrective Action: | | Date: | |
| <u>Venting:</u> | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| <u>Flaring:</u> | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 210256 | Type: | WELL | API Number: | 045-06012 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing, well is not on plunger lift | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|--------------------------------|
| | | Culverts | | | | |
| Compaction | | | | | | Light compaction in some areas |
| Gravel | | | | | | Sparse to none in most areas |
| | | Ditches | | | | |
| | | Compaction | | | | |
| | | Gravel | | | | Sparse |

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| Please refer to Housekeeping for observed compliance issue. | smelserw | 04/11/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 708903515 | Inspection 708903514 Stormwater photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6505513 |
| 708903516 | Inspection 708903514 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6505514 |